

City Burlington

Echo Lake Dam

Field File No. 51.01

Key Sequence No. 602

Walworth County, Wisconsin

Prepared for:

City of Burlington

August 2017

August 8, 2017

Burlington, WI

Re: Post Flood
Dam Safety Inspection Report

Dear Mr. :

Ayres Associates completed an inspection of the Echo Lake Dam on August 3, 2017, in accordance with Wisconsin Department of Natural Resources (WDNR) guidelines. The purpose of this inspection was to assess the condition of the dam following the July floods. We did not review the emergency action plan, operation plan or dam failure analysis. These reviews are still required to satisfy the Owner Responsible Inspection. The following list describes our observations and provides recommendations. Please note that dam structures are referenced from left to right while looking in a downstream direction.

Dam Description and Inspection

The Echo Lake consists, looking left to right, an earthen embankment, a gated spillway with one Tainter gate and a 250 long auxiliary concrete ogee spillway that ties into the railroad embankment. For purposes of this inspection we called the fixed crest spillway the auxiliary spillway. To our knowledge the fixed crest spillway only has flow over it in periods of higher runoff, otherwise most flow is passed through Tainter gate spillway.

This inspection was completed by walking the embankment areas, walking along the top and bottom of the auxiliary spillway and probing under accessible areas of the dam with a survey rod. The entire toe of the auxiliary spillway was probed from the bottom of the spillway. The gated spillway was probed from the left bank and from the right side from the platform above the spillway.

Inspection Findings

1. Embankment Section

The embankment section of the dam did not over top during the July flood. Sediment stains are present, as noted in attached photographs, which show the highwater mark on the embankment. The embankment is in good condition with no observed seepage, rodents, trees, brush or erosion concerns.

2. Tainter Gate Spillway

The Tainter gate was opened during the flood and remained open during this inspection. The gate and operator are relatively old and the City is considering replacing the gate. It

does appear to have functioned properly during the flood and did not sustain any damage.

The downstream spillway was probed to check for scour and undermining. We measured about a 3 foot drop from the edge of the concrete apron of the spillway to the riprap below. We probed under the apron and did not measure any undermining. It appears that some riprap may have been displaced immediately below the spillway and this should be replaced with WisDOT classified heavy riprap.

We also probed along the left training wall and riprap in this area was not displaced.

3. Auxiliary Spillway

The Auxiliary spillway consists of two different shaped sections. The far left end the spillway drops off vertically without an ogee shape. In this area the amount of vertical scour was up to four feet deep (see photo). The majority of the spillway has an ogee shape and in these areas riprap is still at the toe of the spillway base.

We did walk the spillway and probed with the survey rod and noted several areas where the spillway is undermined up to 2 feet, with most areas being about 12 inches.

4. Sidewalk Scour

The sidewalk leading up to the dam suffered scour along the left side. This can be repaired by refilling the area with compacted soil and seeding.

Recommendations

It appears that overall the Echo Lake dam withstood the flood with minimal damage. The displaced riprap and sidewalk scour can be repaired and are typical of routine maintenance required post flood. The undermining noted is likely not a result of this recent flood, but more a long term chronic problem. If the spillway continues to undermine the stability could be compromised and the City should consider grouting the downstream side of the spillway to halt this undermining.

Spillway capacity also is an issue. The dam failure analysis indicates that this dam does not have capacity to pass the 500 year flood. The City should investigate options to increase spillway capacity to pass the 500 year flood.

Please let us know if we can be of further assistance to you.

Sincerely,

Ayres Associates Inc

Christopher T. Goodwin, PE
Manager - Water Resources
Direct: 715.831.7682
Goodwinc@AyresAssociates.com

August 9, 2017
Page 3 of 3

cc: Andrea Stern, WDNR
Greg Governatori

GENERAL (Cont.)

5 Hazard Section

A. D/S Development

Density: ☐ Dense
 Distance: ☐
 Type (Residential, Commercial, Industrial): ☐ Commercial

B. Channel Crossing

Type: ☐ Bridge
 Dimensions: ☐
 D/S distance: 425
 Traffic Level (Local, CTH, STH, Rail Road, STH, Interstate, etc): ☐

C. Distance to nearest D/S community/impoundment:

Name: ☐ Burlington

D. Anticipated Hazard (based on landuse and zoning):

☐ Significant

E. Dam Failure Analysis

Date Completed/Approved: ☐ Jul-15
 Is map available? ☐
 Are map & profile adopted? ☐
 List adoption date: ☐
 Verify validity of failure mode: ☐
 Verify validity of DFA conclusions: ☐

F. Emergency Action Plan

Y N

Comments, Explanation, and Description

M I R

1. Current plan posted? ☒
2. Understood by Operator? ☒
3. Warning systems? ☐
4. Certification of last test? ☐
5. Remote operation? ☐
6. Revision Date? ☐
7. Habitable structures? ☒
8. Recreation areas? ☒
9. Changed hazard potential? ☐
10. New development? ☐
11. Other comments? ☐

Additional Comments:

N= Noted; P= Photo; M= Monitor

I= Investigate; R= Repair

F.F.= Field File; RT = Right; LT = Left

U/S = Upstream; D/S = Downstream

Action Suggestion 1. Requires immediate action

2. Plan to do soon

3. Do when convenient

Dam Inspection Checklist

Burlington Echo Lake Dam

F.F #: 51.01

Date: 08/03/17

Page 2 of 9

EMBANKMENTS										
Description:								Action		
								M	I	R
	Item	N	P	Location on Embankment and Deficiency						
1	Vegetation:	X	No problem							
	A. Trees									
	Quantity (<5, sparse, dense):									
	Diameter:									
	Location:									
	B. Brush									
	Quantity (sparse, dense):									
	Location:									
	C. Ground cover									
	Type (grass, crown vetch, other):			grass						
	Quantity (bare, sparse, adequate, dense):			adequate						
	Appearance (too tall, too short, good):									
2	Erosion	x	No problem		Not applicable		Could not inspect			
	A. Wave erosion (Beaching):									
	Scarp: Length/ Width:									
	Location:									
	B. Runoff Erosion (Gullies)									
	Quantity:									
	Length/ Width/ Depth:									
	Location:									
3	Instabilities	x	No problem		Not applicable		Could not inspect			
	A. Slides									
	Transverse:									
	Longitudinal:									
	Scarp: Length/ Width:									
	Crack Length/ Width:									
	B. Cracks:									
	Transverse:									
	Longitudinal:									
	Length/ Width/ Depth:									
	Location:									
	Other:									
	C. Bulges/ Depressions									
	Size:									
	Height/ Depth:									
	D. Slope (Too Steep)									
	U/S, D/S									
<div style="display: flex; justify-content: space-between;"> <div> <p>N= Noted; P= Photo; M= Monitor</p> <p>I= Investigate; R= Repair</p> <p>F.F.= Field File; RT = Right; LT = Left</p> <p>U/S = Upstream; D/S = Downstream</p> </div> <div> <p>Action Suggestion</p> <p>1. Requires immediate action</p> <p>2. Plan to do soon</p> <p>3. Do when convenient</p> </div> </div>										
Additional Comments:										

Burlington Echo Lake Dam

Dam Inspection Checklist

F.F #: 51.01

Date: 08/03/17

Page 3 of 9

SPILLWAY--PRINCIPAL - FIXED CREST										Action		
Item	N	P	Notes/ Observations							M	I	R
1 Fixed Crest	x		No problem		Not applicable		Could not inspect					
A. Dimensions												
Top Width:			250 feet long									
B. Materials												
			Concrete									
C. Shape (sharp-crested, broad-crested, ogee, chute, gated, overflow, morning glory, dropbox, labyrinth)												
			Ogee									
D. Debris												
Prevention (racks, booms, etc.):			Minimal									
E. Concrete Condition *												
			Adequate for age									
F. Flashboards (none, number):												
Type (Metal, wood):			none									
Dimensions:			none									
Operability:			none									
G. Abutments												
Condition: *			Fair, some spalling. LT abutment is old mill building and gate. RT is railroad grade									
Seepage/wetness:			none observed									
H. Drains												
Type: Weep holes, Relief drains, Other:			No problem									
Flow Rate:			Not applicable									
			Could not inspect									
I. Other												

N= Noted; **P**= Photo; **M**= Monitor
I= Investigate; **R**= Repair
F.F.= Field File; **RT** = Right; **LT** = Left
U/S = Upstream; **D/S** = Downstream

Action Suggestion
1. Requires immediate action
2. Plan to do soon
3. Do when convenient

Controlled = Gated **Uncontrolled** = Overflow

Additional Comments:

* **Type of Concrete Problems:** Spalling, cracks, exposed rebar, misalignment, joints, bug holes, efflorescence, popouts, honeycombing, scaling, craze/map cracks, isolated crack, disintegration, other

Dam Inspection Checklist

Burlington Echo Lake Dam **F.F #:** 51.01 **Date:** 08/03/17 **Page** 5 **of** 9

SPILLWAY-PRINCIPAL - GATES							Action		
Item	N	P	Notes/ Observations				M	I	R
1 Gates			No problem	x	Not applicable	Could not inspect			
A. Types (lift/slide, tainter(radial), stoplogs, leaf, roller, flashboards, needles, other): Number and Size:			One Tainter gate that is fully open during inspection						
B. Stoplogs Dimensions: Condition:			none						
C. Abutments Condition: * Seepage/wetness:			Fair Could not inspect due to full flow through gate opening.						
D. Piers (number, shape) Condition: *			none						
E. Operability Type of Operator: Condition(chain, cables,hoists): Security(locked?): Backup Operator:			Crank with cables Fair access restricted an locked						
F. Access			Good						
G. Condition Rust: Seals (leakage):			Gate is scheduled for replacement.						
H. Ice protection Type (Heaters, Bubblers, Barriers, Other)			none						
I. Debris Prevention (Rack, boom, etc.)			none						
J. Condition of Flowway			good concrete, but much was underwater						
K. Drains Type (Weep holes/ Relief drains/ Other): Flow rate: Location:			could not be inspected due to flow (if present)						
L. Other									
<p>N= Noted; P= Photo; M= Monitor I= Investigate; R= Repair F.F.= Field File; RT = Right; LT = Left U/S = Upstream; D/S = Downstream</p> <p>Action Suggestion 1. Requires immediate action 2. Plan to do soon 3. Do when convenient</p> <p>Controlled = Gated Uncontrolled = Overflow</p> <p>Additional Comments and/or Sketch:</p>									
<p>* Type of Concrete Problems: Spalling, cracks, exposed rebar, misalignment, joints, bug holes, efflorescence, popouts, honeycombing, scaling, craze/map cracks, isolated crack, disintegration, other</p>									

Dam Inspection Checklist

Burlington Echo Lake Dam

F.F #: 51.01

Date: 08/03/17

Page 6 of 9

SPILLWAY--PRINCIPAL - OUTLET EROSION CONTROL & UNDERMINING

Item		N	P	Notes/ Observations			Action		
1	Outlet Erosion Control			No problem	Not applicable	Could not inspect	M	I	R
	A. Type (none, endwall, plunge pool, energy dissipation structure rock lined channel, apron)			Riprap channel					2
	B. Scour			yes, 3' at end of apron, none noted under LT wall					
	C. Material								
	a. Riprap: Avg Diameter: 24" Condition (adequate, sparse, displaced, weathered): Bedding fabric- (Yes/ No):			displaced					
	b. Concrete * Dimensions/Location:			no					
	D. Sidewall/Headwall								
	Misalignment: Location: Description:			LT Side wall, probed and no undermining and riprap at toe.					
	E. Separated Joint / Loss of Joint Material:								
	Location: Description:			not seen					
	F. Natural								2
2	Undermining	x		No problem	Not applicable	x	Could not inspect		
	Location: Description:			Probed under apron and no undermining					
<p>N= Noted; P= Photo; M= Monitor I= Investigate; R= Repair F.F.= Field File; RT = Right; LT = Left U/S = Upstream; D/S = Downstream</p> <p>Action Suggestion 1. Requires immediate action 2. Plan to do soon 3. Do when convenient</p> <p>Controlled = Gated Uncontrolled = Overflow</p> <p>Additional Comments:</p>									
<p>* Type of Concrete Problems: Spalling, cracks, exposed rebar, misalignment, joints, bug holes, efflorescence, popouts, honeycombing, scaling, craze/map cracks, isolated crack, disintegration, other</p>									

Dam Inspection Checklist
Burlington Echo Lake Dam
F.F #: 51.01
Date: 08/03/17
Page 7 of 9

SPILLWAY--AUXILIARY									
Description:								Action	
Item	N	P	Notes/ Observations				M	I	R
1 Dimensions	<input checked="" type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Length/ Width:	250'								
Outfall Slope:									
2 Type (turf, reinforced turf, riprap, block, concrete):	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Concrete Ogee				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3 Signs of usage	<input checked="" type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
(debris, bent grass, etc.):	Flowed in July flood								
4 Vegetation:	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No problem				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
A. Trees	<input type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Quantity (<5, sparse, dense):									
Diameter:									
Location:									
B. Brush	<input type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Quantity (sparse, dense):									
Diameter:									
Location:									
C. Ground cover:	<input type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Type (grass, crown vetch, other)									
Quantity (bare, sparse, adequate dense):									
Appearance (tall, short, good):									
5 Slope protection	<input type="checkbox"/>	<input type="checkbox"/>	Not applicable				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
A. Type (none, riprap, wave berm, concrete slabs, other):	<input type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Condition:									
6 Erosion	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No problem	<input type="checkbox"/>	Not applicable	<input type="checkbox"/>	Could not inspect	<input type="checkbox"/>	<input type="checkbox"/>
A. Wave erosion (beaching):	<input type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Scarp: Length/ Width:									
Location:									
B. Runoff erosion (Gullies)	<input type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Quantity:									
Length/ Width/ Depth:									
Location:									
7 Instabilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	No problem	<input type="checkbox"/>	Not applicable	<input type="checkbox"/>	Could not inspect	<input type="checkbox"/>	<input type="checkbox"/>
A. Slides	<input type="checkbox"/>	<input type="checkbox"/>					<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Transverse Length:									
Longitudinal Length:									
Scarp: Length/ Width:									
Location:									
Crack Length/ Width:									
Location:									
N= Noted; P= Photo; M= Monitor I= Investigate; R= Repair F.F.= Field File; RT = Right; LT = Left U/S = Upstream; D/S = Downstream									
Action Suggestion 1. Requires immediate action 2. Plan to do soon 3. Do when convenient									
Additional Comments:									
* Type of Concrete Problems: Spalling, cracks, exposed rebar, misalignment, joints bug holes, efflorescence, popouts, honeycombing, scaling, craze/map cracks, isolated crack, disintegration, other									
Dam Inspection Checklist									
Burlington Echo Lake Dam			F.F #: 51.01		Date: 08/03/17		Page: 8 of 9		

Inspection Echo Lake Dam (Key Sequence No. 602)
August 3, 2017



Burlington Echo Lake Dam
Photo During Flood (Taken July 25)



Burlington Echo Lake Dam
Auxiliary spillway viewed from left



Burlington Echo Lake Dam
Auxiliary spillway near vertical section



Scour depth of 4'

Burlington Echo Lake Dam
Auxiliary spillway near vertical section



Burlington Echo Lake Dam
Auxiliary spillway from viewed from right



Burlington Echo Lake Dam
Typical undermining of 1 foot under spillway



Burlington Echo Lake Dam
Spillway undermining



Burlington Echo Lake Dam
Embankment